

Technical Notes

Power Fuse

Tech Note Number: 541 Total number of pages: 1

Date: July 9, 2009

Applicable Models: AnaJet FP-125 and Sprint printer series

The symptoms of a blown fuse are as follows:

The printer will not turn on from the back of the switch.



What you will need:

- A small flat head screw driver
- 2 new fuses

Steps for Replacing:

Step1: Unplugged the power cord on the printer. Next pull the black casing back.



Step 2: With the screw driver remove the red fuse box.



Step 3: Replace the fuses with new ones.

